

**Newsletter No 1** 

# **Glory Revealed**


# St German's Cathedral:

'Treasuring the Past, Serving the Present, Sustaining the Future'

Phase 1: The Story so far September 2023 ...

... So far we have funding for £1.5m of work i.e. the floor and basic structural and electrical work ONLY.

Blue areas not yet funded



# What work has been undertaken since work began in August?

• All wooden flooring removed and sold for the restoration of Bishopscourt

New pedestrian entrance created from Derby Road (no photo)

**Building:** New trench dug across Cathedral car park for three phase electricity cable to Cathedral from Corrin Hall intake. (2 spurs for future electric car charging point inserted)

**Photo:** Cathedral car park looking up the roadway in the middle of the Franciscan Garden



**Building:** Debris removed from under floor and ground compacted (sandstone retained for new entrance to the Cathedral at Derby Road bus stop)

Central heating pipework removed

**Photo:** South Transept from the canons boards

 New opening made in screen to North Vestry (no picture)



**Building:** Wainscoting required to be removed as sitting on wooden floor (stored for reinstatement) Each board is numbered for re-instatement.

Void under removed wooden floors filled with Type 1 stone compacted.

Photo: South Aisle

#### Note:

- Joists protruding under wainscoting
- Note compacted floor awaiting next layers

#### **Extras:**

- Removal and re-instatement of wainscoting
- Main doors hinges have cracked the stonework. Re-do hinges and repair stonework.





**Building:** New opening to boiler house created

**Photo:** View from boiler house to south transept. Note canons boards through the opening.

**Extra:** Asbestos discovered in boiler house ceiling



**Building:** Service ducts laid in lower levels of the floor.

**Photo:** from South Transept to South Aisle.

### **Notes:**

- pipes breaking through gangways with tiles
- Tiles removed for service trunking to go under gangways reinstated.



**Building:** Tiles reinstated

# **Notes:**

- Tiles once removed for service trunking reinstated.
- Planners require tiling to be protected



New electricity (light and power) control centre created at rear of organ

**Photo:** View towards what was once south Vestry internal door



**Building:** Service trunking pinned to walls

**Photo:** View from south Transept along south Aisle

#### Note:

- Service ducts coming from floor
- Two tracks of service ducts which will be behind wainscoting carrying audio visual and electrical wiring.
- Dado rail removed and stored for re-instatement.



Building: New opening to new kitchen created

**Photo:** View from South Transept. You can see the rafter on the ceiling of the South Vestry

## Note:

- girders and props temporarily holding up the wall
- Diamond saw for cutting walls

Extra: Dry rot discovered in the south vestry floor

Block up opening between toilets and North Vestry



If you would like to assist us in this development, please contact the Dean: The Very Revd Nigel Godfrey: T: 01624 844 830 or E: dean@cathedral.im